

July 13, 2015 3-11 Shift Notes

## **BASF EMPLOYEES**

232 Last Recordable 166 Last Lost Time

14 Days To RC Audit

### #1 MED / AI 3992 next:

Removing all locks for the dust collectors on the roof. Started up the F-1 scrubber and hope to start on second shift. Powder room raw brought over (Cat C1).

### #1 RC / Al 3992 next:

Starting the F-1 up late on first shift. Attempting to light calciner late on first shift.

### Exhaust to F1

### #2 MED line / Cu 0860:

On hold for Justin.

# #2 RC/ Clean for Cu 1202 pills:

Will just need to make sure calciner is reversed, side door cleaned out, and screens changed out per the MOD. Then we will need to get Lot 2 of the 1201 material from the North end and feed it first.

## Exhaust to F1

## #3 MED line / Clean for D-1702:

Follow clean up sheet that has been provided by John.

# #3 RC / X 253:

Able to get the CTO lit mid shift and is coming up to temperature. Trying to light calciner late on first shift. Will need to refeed Bag #3 and oversize drums from the X 253 run. Bag 3 to be remade, and the balance into bag 7 (partial) and continue into bag 8 if needed. The screen has been changed per Justin's e-mail to a 3 mesh.

# **Exhaust to CTO**

#### #4 RC / D-1145:

Performed walk through and started the feed at the beginning of first shift.

### **Exhaust to 4 DC**

#### #5 RC / Cu 3818:

Performing walk through late on first shift and starting the feed. Copper Carb unloaded from truck at dock.

#### Exhaust to 5 DC

## #6 RC & Dryer / D 1781 next

Dryer and calciner back together, need MOD and screen information.

# **Exhaust to Sly Scrubber**

## West Pfaudler / D-1145

Should be able to resume batches on second shift if National dryer can stay lit(electrician scheduled to look at it late on first shift).

## East Pfaudler/ D 1781 next:

D 1780 base moved from truck dock to 3<sup>rd</sup> floor. Lid re-installed on pfaudler. Start batches when calciner/dryer ready.

	6 Tank:
Tank empty	
	7 Tank:
Tank empty	

National Dryer / D-1145
Kirk looking into communication issues late on first.

	PK Blender:	
Hold for instructions.		

Abbe Blender:

## Tower 3 / Pd 0930:

Empty and on hold, more Pd 0930 after shut down. PSSR to be performed on Tuesday. Repacks can be performed when we get word that the material has been received.

## Tower 6 / DPT 0101:

Empty and on hold, more DPT after shut down. PSSR to be performed on Tuesday.

# North Screener /:

Down

### South Screener / DPT 0101:

DPT screening done, hold until after shutdown.

# #2662 (west) Pill Machine / Al-3915:

Continue running, will need more pill mix. No Catapal for now. May be a while.

## #2664 (east) Pill Machine / Al-3915:

Continue rebuilding

## TK #2 / V 2010:

Down

### TK #4 / Cu 2508:

Unable to light. Maintenance notified and a work order written on first shift.

## Harrop Kiln / Al 3920:

Kiln lit on first shift with the help of an electrician.

# Building 27 Belt Filter / 5020 next:

Will be starting a run of 5020 right after shutdown. Bringing Britesorb to the second floor at 1:30. Jeff Lewis looking into a possible way to pump solutions up to the second floor instead of raising through the overhead door.

Call outs required on 1 through 10.

- 1) West Pfaudler/National Dryer/#4 RC
- 2) East Pfaudler/HC-11 Dryer/Calciner
- 3) #5 Calciner
- 4) #3 MED/#3RC
- 5) Harrop Kiln
- 6) #2 MED/#2 RC
- 7) #1 MED/#1RC
- 8) Horne Tabletting
- 9) #2 Tunnel Kiln
- 10) Reduction Towers
- 11) Reduction Screening